

## **Habitability Inspection Guidelines**

Adequacy of space for the individuals being served.

Adequate place to sleep,

• Indoor air quality and ventilation.

Functioning windows, HVAC distribution and return ducts

Adequacy of safe water supply.

City water supply or whole house filtration system

• Cleanliness of the setting, including kitchen, bathroom, and living spaces.

Broom clean, free from rodent / pest droppings etc, no visible mold, lived in stuff on floor ok

• Adequacy of electrical service, outlets, and lighting and absence of electrical hazards.

100-amp minimum electrical service, 2 duplex receptacles per bedroom, 1 switched light source per bedroom

• Any potential lead exposure.

No pealing paint on buildings built prior to 1978

- Any conditions that might affect the health of the individuals being served. Environmental concerns; damaged asbestos, etc.
- Any conditions that might affect the safety of the individuals being served. Smoke detectors need to be installed in each sleeping room, in hallways outside sleeping room and on each level with stairway access. Carbon monoxide detectors need to be installed within 10 feet of each sleeping room. Smoke and carbon monoxide detectors can be battery operated. Handrails must be installed on any stairway with over 3 steps.
- The condition of the building's foundation and exterior, including accessibility; and Foundation, siding and roof and doors must be functional
- The condition and functionality of equipment for heating, cooling, ventilation, and plumbing.

All must be functional with no plumbing leaks. Must have hot and cold running water at all appropriate fixtures.

If the building does not pass the inspection and the correction will be simple to make, we will work with you. You may be able to send a text photo proof of correction to obtain the signed report without a re-inspection fee. For more extreme cases each case will be a case-by-case basis. For more information, please contact us at **651-489-4633**.